OMB Control No.: 2127-0004

Recall Quarterly Report

20V-189

Manufacturer Name: Subaru of America, Inc.

NHTSA Recall No. / MFR Recall No.: 20V-189 /WRC-20

Recall Subject: Rear Seat Belt Assemblies May Not Lock As Intended

Owner Notification Beginning Date : APR 15, 2020

Owner Notification End Date: APR 15, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 23, 2020	2020-2	4,862	2,529	0	0

This Document Last Updated: JUL 28, 2020

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012).

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.