OMB Control No.: 2127-0004

Recall Quarterly Report

20V-216

Manufacturer Name: Shyft Group

NHTSA Recall No. / MFR Recall No.: 20V-216 /20-05

Recall Subject: License Plate Lamp Incorrectly Installed/FMVSS 108

Owner Notification Beginning Date : MAY 05, 2020

Owner Notification End Date: MAY 05, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	OCT 21, 2020	2020-3	50	43	0	0
1	JUL 23, 2020	2020-2	50	32	0	0

This Document Last Updated: NOV 03, 2020

Definitions:

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the $3^{\rm rd}$ quarter of 2012).

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.