



August, 2020

*** * * IMPORTANT SAFETY RECALL REMINDER * * ***

According to our records, your 2020 Expedition has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: 20S17 - FRONT PASSENGER SEATBELT TENSION SENSOR

What is the issue? On your vehicle, certain attachment bolts for the seats, seatbacks, seatbelt buckles and/or seatbelt anchors may have been improperly hardened during manufacturing and could be more susceptible to fracture. If a seat, seatback, or seatbelt anchor attaching bolt fractures, the structural integrity of the seat or the seatbelt system's performance may be compromised in a sudden stop or crash, increasing the risk of injury.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: www.Fordowner.com.

Thank you for your attention to this very important matter.

Augusto de, 2020

*** * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * ***

Seg nuestros registros, no se realizaron en sur 2020 Expedition las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 20S17 - SENSOR DE TENSION DEL CINTURÓN DE SEGURIDAD DEL PASAJERO DELANTERO

¿Cuál es el problema? En su vehículo, ciertos tornillos de unión de los asientos, respaldos, hebillas del cinturón de seguridad o anclajes del cinturón de seguridad no presentan una rigidez adecuada de fábrica y podrían fracturarse. Si se fractura el tornillo de unión de un asiento, respaldo o anclaje del cinturón de seguridad, la integridad estructural de este asiento o el desempeño del sistema del cinturón de seguridad podría verse comprometido en una parada repentina o choque, lo cual aumenta el riesgo de sufrir lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: www.Fordowner.com.

Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

C / 0336 / 000000000000159 / A



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

