



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

April 21, 2020

Mr. Fred Imundo
Compliance Coordinator
Navistar, Inc.
2701 Navistar Dr.
Lisle, IL 60532

NEF-150MR
20V-219

Subject: Fuel Heater May Overheat and Cause Fire

Dear Mr. Imundo:

This letter serves to acknowledge Navistar, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

IC BUS/1300 FBC/2018-2019
IC BUS/CE/2018-2021
IC BUS/HC/2018-2019
IC BUS/TC/2019-2021
INTERNATIONAL/DURASTAR/2017-2020
INTERNATIONAL/HV/2018-2021
INTERNATIONAL/MV/2018-2021
INTERNATIONAL/WORKSTAR/2017-2020

Mfr's Report Date: April 17, 2020

NHTSA Campaign Number: 20V-219

Components:

FUEL SYSTEM, DIESEL: PRE-HEATER

Potential Number of Units Affected: 27,421

Problem Description:

Navistar, Inc. (Navistar) is recalling certain 2017-2020 International WorkStar and International DuraStar, 2018-2019 IC 1300 FBC Commercial and IC HC Commercial, 2018-2021 IC CE Commercial, International MV and International HV, and 2019-2021 IC TC Commercial buses with Cummins B6.7 diesel engines with a fuel module option number FS90301 or FS90453. The electric fuel heater within the fuel module may overheat and cause plastic in the fuel heater to melt and potentially catch fire. It may also lead to engine stalling.

Consequence:

A fire increases the risk of injury. An engine stall can increase the risk of a crash.

Remedy:

The remedy for this recall is still under development. Cummins will notify the affected Navistar customers. The manufacturer has not yet provided a notification schedule. Owners may contact Cummins customer service at 1-800-286-6467.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

We understand that Navistar will not be filing quarterly recall completion rates for this campaign.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Chief, Recall Management Division
Office of Defects Investigations
Enforcement