

Recall Quarterly Report

20V-231

Manufacturer Name : McLaren Automotive Incorporated
NHTSA Recall No. / MFR Recall No. : 20V-231 /
Recall Subject : Foam Pad May Retain Moisture and Corrode Fuel Tank
Owner Notification Beginning Date : JUN 17, 2020
Owner Notification End Date: JUN 17, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 21, 2020	2020-2	2,763	658	0	0

This Document Last Updated : JUL 23, 2020

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
Recall Population : The total number of products recalled by the manufacturer.
Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.
Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.
Total Removed : Products that have been scrapped, stolen, or exported.