

ADDITIONAL VINS AFFECTED BY RECALL ACTION 579



Notice Information

| | |
|--------------|--|
| Ref | 15463 |
| Posted Date: | |
| Posted To: | General Manager / Business Owner, Technician, Service Leader / Advisor, Accounts / Admin |
| Subject: | Service/Technical |

TOL NOTICE (US&CA) – July 30, 2020

TOL Ref. # 15463-SVC

ADDITIONAL VINS AFFECTED BY RECALL ACTION 579

This notice is a follow-up on the initial attached campaign announcement notice. Triumph has increased the VIN range of affected motorcycles for this campaign.

Issue 4 of Safety Recall Action Notice (SRAN) 579 has been saved in the TriumphOnline Service Bulletin library. Issue 4 is currently in English only.

Issue 4 includes an extended VIN range relating to Speed Triple S and Speed Triple RS models. The new VIN range for these Speed Triple models is From VIN 800262 to VIN AC5827.

Translated copies of Issue 4 will be posted to the Service Bulletin library in approximately ten working days' time and will replace the current Issue 3 documents.

Triumph will be writing to the additionally affected customers in the next few days for any retailed VINs.

U.S. LAW PROHIBITS THE DELIVERY OF A RECALLED MOTORCYCLE UNDER A SALE OR LEASE UNTIL THE REMEDY HAS BEEN PERFORMED.

Finally, please note that if you wish to order replacement brake pads for normal service use, then please do so. Normal stock orders will be accepted and processed by Triumph.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.