OMB Control No.: 2127-0004

Part 573 Safety Recall Report

20V-250

Manufacturer Name: National Van Builders, Inc.

Submission Date: MAY 05, 2020 NHTSA Recall No.: 20V-250 Manufacturer Recall No.: 20E-004



Manufacturer Information:

Manufacturer Name: National Van Builders, Inc.

Address: 80 Pine Street

Attleboro MA 02703

Company phone: 800-527-7477

Population:

Number of potentially involved : 5 Estimated percentage with defect : 50 %

Vehicle Alterer Information:

Vehicle 1: 2019-2020 Ford Transit

Descriptive Information: Safety Recall Notice No 20E-004 was received From Freedman Seating Company

on April 9, 2020 indicating that certain GO-ES foldaway seats manufactured between August 2019 and January 2020 may have been manufactured using seat belt retractors that may not be compliant to FMVSS 209. National Van identified all vehicles that were built with Freedman GO-ES foldaway seats installed and

sold between August 1, 2019 and April 15, 2020.

Production Dates: AUG 01, 2019 - APR 15, 2020

Vehicle 2: 2019-2019 Ram Promaster

Descriptive Information: Safety Recall Notice No. 20E-004 received from Freedman Seating Company

Production Dates: NOV 01, 2019 - APR 15, 2020

Description of Defect:

Description of the Defect: Certain vehicles altered by National Van Builders that included the installation

of Freedman GO-ES foldaway seats which may have been manufactured by

Freedman Seating Company with seat belt retractors that may not be

compliant to FMVSS 209.

FMVSS 1: 209 - Seat belt assemblies

FMVSS 2: NR

Description of the Safety Risk: Failure of the seat belt retractor to operate as required in FMVSS 209 may

cause injury.

Description of the Cause: Certain GO-ES foldaway seats may have been manufactured by Freedman

Seating Company with seat belt retractors that do not meet FMVSS 209 and

subsequently installed in vans altered by National Van Builders.

Identification of Any Warning none that we are aware of

that can Occur:

Involved Components:

Component Name: Freedman GO-ES Foldaway seat

Component Description: 1 or 2 passenger Foldaway Seat

Component Part Number: 43705, 44000, 44001

Supplier Identification:

Component Manufacturer

Name: Freedman Seating Company

Address: 4545 W. Augusta Blvd

Chicago ILLINOIS 60651

Country: United States

Chronology:

Safety Recall Notice No 20E-004 was received from Freedman Seating Company on April 9, 2020 indicating that certain GO-ES foldaway seats manufactured by Freedman between August 2019 and January 2020 may have been manufactured with a seat belt retractor that may not meet FMVSS 209. Vans altered by National Van Builders with foldaway seats between August 1 and April 15 were identified.

Description of Remedy:

Description of Remedy Program: Freedman Seating Company will facilitate the inspection and any

necessary repairs. Videos illustrating the inspection procedure can be found at www.freedmanseating.com/instructions/m2k-jss-retractor. After inspection, if the seat belt retractors are found non-compliant, Freedman Seating Company will send replacement(s) via information submitted on the online form provided with the inspection procedure above. Freedman will reimburse the cost of repairs including parts and labor of \$25.00 per

belt.

How Remedy Component Differs Replacement retractor that is FMVSS 209 compliant

from Recalled Component:

Identify How/When Recall Condition All seats in-house were inspected using the procedure proscribed by

was Corrected in Production: Freedman Seating Company and none were found to be defective.

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date : MAY 26, 2020 - JUN 09, 2020 Planned Owner Notification Date : MAY 26, 2020 - JUN 02, 2020

Purchaser Information:

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name:

Address:

Country : Company Phone :

^{*} NR - Not Reported