

**Recall Quarterly Report****20V-277**

**Manufacturer Name :** Yamaha Motor Corporation, USA  
**NHTSA Recall No. / MFR Recall No. :** 20V-277 /990137  
**Recall Subject :** Insufficiently Tightened Cylinder Head Nuts  
**Owner Notification Beginning Date :** MAY 29, 2020  
**Owner Notification End Date:** JUN 01, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JAN 04, 2021	2020-4	3,116	517	0	0
2	OCT 02, 2020	2020-3	3,116	443	0	0
1	JUL 08, 2020	2020-2	3,116	55	0	0

This Document Last Updated : JAN 05, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.