

# Part 573 Safety Recall Report

## 20V-284

**Manufacturer Name :** REV Ambulance Group Orlando, INC.**Submission Date :** MAY 20, 2020**NHTSA Recall No. :** 20V-284**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : REV Ambulance Group Orlando, INC.

Number of potentially involved : 100

Address : 2737 N. Forsyth Road

Estimated percentage with defect : 88 %

Winter Park FL 32792

Company phone : 800-628-8178

**Vehicle Information :**

Vehicle 1 : 2018-2020 REV Ambulance Group Type I

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : REV's Type I ambulances equipped with Liquid Springs suspension systems are subject to recall. Liquid Springs relayed quantity and serial numbers.

Production Dates : JAN 01, 2018 - MAY 01, 2020

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The affected system component is the rear brake caliper flexible line which may be causing brake caliper to wear due to contact suspension components.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Continued use with rear flexible line may result in partial or complete loss of rear service brakes.

Description of the Cause : NR

Identification of Any Warning NR  
that can Occur :**Involved Components :**

Component Name 1 : DS135RS3A, DS135RS3AF, DS135RS3-DM

Component Description : Rear Brake Caliper Flexible Lline

Component Part Number : NR

### Supplier Identification :

#### Component Manufacturer

Name : Liquid Springs LLC

Address : 4899 E 400 S

Lafayette INDIANA 47905

Country : United States

### Chronology :

May 2020 Liquid Springs LLC made REV Group Orlando aware of a Liquid Spring RAM rear brake caliper flexible Line issue.

### Description of Remedy :

Description of Remedy Program : If vehicle is equipped with Liquid Springs suspension system with the serial number range, customer will need to arrange service to have the rear brake caliper flexible lines inspected and modified to address the potential wear issue, at no cost to the customer.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

### Recall Schedule :

Description of Recall Schedule : REV Group Orlando will begin to notify dealers and customers in July or sooner.

Planned Dealer Notification Date : JUL 01, 2020 - JUL 15, 2020

Planned Owner Notification Date : JUL 01, 2020 - JUL 15, 2020

\* NR - Not Reported