

June 26, 2020

Mr. Mike Becker Director of Corporate Compliance Forest River, Inc. 2324 Century Drive Goshen, IN 46528

Subject: Propane Gas Line may be Damaged by Sharp Edges

Dear Mr. Becker:

This letter serves to acknowledge Forest River, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: FOREST RIVER/CHEROKEE WOLF PACK/2021

Mfr's Report Date: June 26, 2020

NHTSA Campaign Number: 20V-377

Components: EQUIPMENT:RECREATIONAL VEHICLE:LPG LINES AND FITTINGS

Potential Number of Units Affected: 59

Problem Description:

Forest River, Inc. (Forest River) is recalling certain 2021 Cherokee Wolf Pack toyhaulers, model CKF325PACK13. The propane gas line may be routed around sharp edges which may cause a propane leak.

Consequence:

A propane leak can increase the risk of a fire.

Remedy:

Forest River will notify owners and dealers will reroute the propane line and/or replace it if necessary, free of charge. This recall is expected to begin August 5, 2020. Owners may contact Forest River customer service at 1-260-499-2100. Forest River's number for this recall is 73-1182.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150KL 20V-377

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kristin Lepper who may be reached by phone at 202-366-5227, or by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff Chief, Recall Management Division Office of Defects Investigations Enforcement

