vor		olvo Car Customer Service	QB Instruction VC	C-519962-2		
Title		Passenger seat belt height adjuster	Page	1 (6)		
Action		Product fix	Operation number:	97704-3		
Issue	Date	Reason				
1 2020-10 F		0 First issue	First issue			

Affected vehicles

Model year	Model	Partner group
2011, 2012,	S60 (11-18)	America
2013, 2014,		
2015, 2016,		
2017, 2018		
2016, 2017,	S60 Cross Country	America
2018		
2014, 2015,	V60 (-18)	America
2016, 2017,		
2018		
2015, 2016,	V60 Cross Country	America
2017, 2018	(-18)	

Materials						
Materials	Qty.	Part No.	Notes			
Block	1.0	32328849				


Click on this link to view a short video on the "End Fitting/Block" repair method

https://youtu.be/y2egSPJvdww

Removal


Note! Removal steps in this procedure may contain installation details. **Color symbols** Note! This colour chart displays (in colour print and electronic version) the importance of the different colours used in the images of the method steps. (1) (3) (5) 1. Used for focused component, the component with which you will do something. (2) 2. Used as extra colors when you need to show 4 6 or differentiate additional parts. 3. Used for attachments that are to be removed/installed. May be screws, clips, connectors, etc. 2 4. Used when the component is not fully removed from the vehicle but only hung to the side. 5. Used for standard tools and special tools. 6. Used as background color for vehicle components.

Applies to the passenger side




QB Instruction VCC-519962-2

Page 4 (6)



Installation

Applies to the passenger side






QB Instruction VCC-519962-2

Page 6 (6)

Install the clip(s).





To install, reverse the removal procedure.