

Recall Quarterly Report**20V-391****Manufacturer Name :** Airstream, Inc.**NHTSA Recall No. / MFR Recall No. :** 20V-391 /**Recall Subject :** Bolts Securing Suspension Spring May Be Too Long**Owner Notification Beginning Date :** AUG 26, 2020**Owner Notification End Date:** AUG 26, 2020

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	APR 27, 2021	2021-1	145	107	0	0
2	FEB 01, 2021	2020-4	145	105	0	0
1	OCT 28, 2020	2020-3	35	11	0	0

This Document Last Updated : APR 29, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.