OMB Control No.: 2127-0004

Recall Quarterly Report

20V-394

Manufacturer Name: Daimler Coaches North America

NHTSA Recall No. / MFR Recall No.: 20V-394 /75.00U20104A
Recall Subject: Engine Compartment Flap Hinge Improperly Welded

Owner Notification Beginning Date : AUG 28, 2020

Owner Notification End Date: AUG 28, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	APR 01, 2021	2021-1	55	39	0	0
2	JAN 04, 2021	2020-4	55	37	0	0
1	OCT 05, 2020	2020-3	55	16	0	0

This Document Last Updated: APR 01, 2021

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.