

**Recall Quarterly Report****20V-394****Manufacturer Name :** Daimler Coaches North America**NHTSA Recall No. / MFR Recall No. :** 20V-394 /75.00U20104A**Recall Subject :** Engine Compartment Flap Hinge Improperly Welded**Owner Notification Beginning Date :** AUG 28, 2020**Owner Notification End Date:** AUG 28, 2020

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JAN 04, 2021	2020-4	55	37	0	0
1	OCT 05, 2020	2020-3	55	16	0	0

This Document Last Updated : JAN 06, 2021

**Definitions :**Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.