## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

20V-403

Manufacturer Name: Mitsubishi Motors North America, Inc. NHTSA Recall No. / MFR Recall No.: 20V-403 /SR-20-004 Recall Subject: Inoperative Right Rear Seat Belt Buckle Owner Notification Beginning Date: SEP 01, 2020

**Owner Notification End Date: SEP 01, 2020** 



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JAN 31, 2021	2020-4	177,000	47,157	5,508	2,105
1	OCT 30, 2020	2020-3	177,000	24,625	2,819	1,977

This Document Last Updated: FEB 03, 2021

## **Definitions:**

 $Report\ Quarter:\ The\ quarter\ the\ manufacturer\ is\ reporting\ recall\ completion\ figures\ (e.g.\ 2012-3\ means\ the\ 3^{\bf rd}\ quarter\ of\ 2012).$ 

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.