

# Recall Quarterly Report

## 20V-433

**Manufacturer Name :** Tiffin Motorhomes, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 20V-433 /  
**Recall Subject :** Wiper Control Module may be Wired Improperly  
**Owner Notification Beginning Date :** AUG 13, 2020  
**Owner Notification End Date:** AUG 18, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	NOV 25, 2020	2020-3	643	137	0	0

This Document Last Updated : NOV 27, 2020

### Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).  
**Recall Population :** The total number of products recalled by the manufacturer.  
**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.  
**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.  
**Total Removed :** Products that have been scrapped, stolen, or exported.