

Recall Quarterly Report**20V-449**

Manufacturer Name : Mercedes-Benz USA, LLC
NHTSA Recall No. / MFR Recall No. : 20V-449 /2020080015
Recall Subject : Seat Belt Warning System Not Operating Properly
Owner Notification Beginning Date : SEP 08, 2020
Owner Notification End Date: SEP 08, 2020



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 4 | JUL 14, 2021 | 2021-2 | 56 | 32 | 0 | 0 |
| 3 | APR 20, 2021 | 2021-1 | 56 | 26 | 0 | 0 |
| 2 | JAN 14, 2021 | 2020-4 | 56 | 23 | 0 | 0 |
| 1 | OCT 19, 2020 | 2020-3 | 56 | 9 | 0 | 0 |

This Document Last Updated : AUG 12, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.