



December, 2020

**\* \* \* IMPORTANT SAFETY RECALL REMINDER \* \* \***

According to our records, your 2020 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number** 20S40 - WRONG B+ STARTER NUT  
**and Description:**

**What is the issue?** On your vehicle, an incorrect attachment nut used to fasten the positive battery cable (B+) to the starter motor may have been installed during production.  
This may result in a grinding noise upon engine start-up, a no start condition, and/or electrical arcing, which may increase the risk of a fire.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [www.owner.ford.com](http://www.owner.ford.com).

Thank you for your attention to this very important matter.

December de, 2020

**\* \* \* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \* \* \***

SegUR nuestros registros, no se realizaron en su 2020 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** 20S40 - TUERCA DEL MOTOR DE ARRANQUE B+ INCORRECTA

**¿Cuál es el problema?** Es posible que en su vehículo, en la fase de producción, se haya instalado una tuerca de unión incorrecta para conectar el cable positivo de la batería (B+) al motor de arranque.  
Esto podría generar un chirrido al arrancar el motor, una condición de ausencia de arranque o un arco eléctrico, lo cual podría aumentar el riesgo de incendio.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [www.owner.ford.com](http://www.owner.ford.com).

Gracias por su atención en este asunto sumamente importante.



P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

D / 0085 / 000000000000103 / A



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

