

Recall Quarterly Report**20V-470**

Manufacturer Name : Ford Motor Company
NHTSA Recall No. / MFR Recall No. : 20V-470 /20S41
Recall Subject : Rear Coil Springs may Fracture
Owner Notification Beginning Date : NOV 04, 2020
Owner Notification End Date: NOV 04, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 28, 2021	2020-4	2,965	1,592	81	0

This Document Last Updated : JAN 28, 2021

Definitions :

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.