## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

20V-471

Manufacturer Name: BMW of North America, LLC NHTSA Recall No. / MFR Recall No.: 20V-471 / Recall Subject: Fuel Pump Flange may Leak

**Owner Notification Beginning Date:** JAN 18, 2021

**Owner Notification End Date: JAN 18, 2021** 



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	OCT 25, 2021	2021-3	16,926	5,560	0	0
2	JUL 30, 2021	2021-2	16,926	4,409	0	0
1	APR 30, 2021	2021-1	16,926	2,740	0	0

This Document Last Updated: OCT 26, 2021

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.