

Recall Quarterly Report**20V-534**

Manufacturer Name : Tiffin Motorhomes, Inc.
NHTSA Recall No. / MFR Recall No. : 20V-534 /
Recall Subject : Steering Pinch Bolts Not Tightened Properly
Owner Notification Beginning Date : AUG 27, 2020
Owner Notification End Date: SEP 02, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 22, 2021	2020-3	8	8	0	0

This Document Last Updated : JUL 22, 2021

Definitions :

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.