

**Recall Quarterly Report****20V-655****Manufacturer Name :** Forest River, Inc.**NHTSA Recall No. / MFR Recall No. :** 20V-655 /15-1245**Recall Subject :** Furnace Fresh Air Intake Sleeve Too Short**Owner Notification Beginning Date :** NOV 06, 2020**Owner Notification End Date:** NOV 06, 2020

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 18, 2021	2020-4	69	10	0	0

This Document Last Updated : JAN 19, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.