## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

20V-656

**Manufacturer Name:** Forest River, Inc.

**NHTSA Recall No. / MFR Recall No.:** 20V-656 /400-1243

**Recall Subject:** Antenna Wing may Detach

**Owner Notification Beginning Date :** NOV 23, 2020

**Owner Notification End Date:** NOV 25, 2020



| Report # | Submission Date | Report<br>Quarter | Recall<br>Population | Total<br>Remedied | Total<br>Unreachable | Total<br>Removed |
|----------|-----------------|-------------------|----------------------|-------------------|----------------------|------------------|
| 2        | APR 06, 2021    | 2021-1            | 1,150                | 238               | 0                    | 0                |
| 1        | JAN 18, 2021    | 2020-4            | 1,150                | 88                | 0                    | 0                |

This Document Last Updated: APR 09, 2021

## **Definitions:**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{\rm rd}$  quarter of 2012).

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.