

# **AUDI DEALER COMMUNICATION**

## Repair Available - Safety Recall 70H8 / Deformation Element

This notice is for:

- Dealer Principal
- ✓ Parts Manager

Service Manager

✓ Warranty Administrator

✓ General Manager✓ Sales Managers

November 12, 2020

- Parts Manager
- ✓ Service Advisor

✓ Technicians

Issue:

Date:

According to the requirements of FMVSS 201u, the head injury criterion (HIC) shall not exceed 1000. During one Conformity of Production (CoP) test, this value measured 1,007 (which exceeds the required maximum of 1,000) and therefore presents a noncompliance with FMVSS201u. Theoretically there could be an increased risk if an unbelted passenger's head contacts the C-pillar in a crash.

## Repair:

- REPAIR AVAILABLE November 13, 2020 Replace the deformation element on the driver's and passenger's side C-pillar.
- See ELSA/ServiceNet for complete repair & claiming instructions
- Check daily campaign open inventory report or OMD for affected vehicles in inventory
- Repair every affected inventory vehicle <u>before delivery to consumers</u>.

#### Parts Allocation:

Dealers will be sent an initial allocation prior to customer notification. If no initial allocation was received, please reference the Repair Projection Tool in the campaign circular to view your potential VIN population.

## **Affected Vehicles**

Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count
USA	2018	2020	Q7	94,144

<sup>\*</sup>Counts reflect overall population; some vehicles may have already been repaired. Check Campaigns/Actions screen in Elsa <u>on the day of repair</u> to verify that a VIN qualifies for repair under this action. Elsa is the <u>only</u> valid campaign inquiry & verification source.

### Notes:

- Schedule owner repairs immediately
- Owner mailing November 2020

## IMPORTANT REMINDER: VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS

New Vehicles in Dealer Inventory: It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

<u>Pre-Owned Vehicles in Dealer Inventory:</u> Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.

#### -END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Audi Public Relations.

Audi Customer Protection 70H8 DLR LAUNCH