

**Recall Quarterly Report****20V-696**

**Manufacturer Name :** Terex South Dakota, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 20V-696 /SN687  
**Recall Subject :** Rotation Bearing Bolts May Fail  
**Owner Notification Beginning Date :** NOV 24, 2020  
**Owner Notification End Date:** NOV 24, 2020



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 1        | JAN 06, 2021    | 2020-4         | 40                | 3              | 0                 | 0             |

This Document Last Updated : JAN 07, 2021

**Definitions :**

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.