

**Recall Quarterly Report****20V-698****Manufacturer Name :** Toyota Motor Engineering & Manufacturing**NHTSA Recall No. / MFR Recall No. :** 20V-698 /20TA15**Recall Subject :** Headlights Can Be Misadjusted/FMVSS 108**Owner Notification Beginning Date :** JAN 06, 2021**Owner Notification End Date:** JAN 06, 2021

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 21, 2021	2021-1	413	336	0	0

This Document Last Updated : MAY 05, 2021

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.