IMPORTANT SAFETY RECALL



NHTSA RECALL: 20V727 CANADA RECALL: 2020-563 FR ID: 51-1259

<<CITY>>, <<ST>> <<ZIP-XXX>>

<<DEALERNAME>>

<<ADDRESS>>

DEPARTMENT OF COMPLIANCE VEHICLE SAFETY AND RECALL MANAGEMENT BUILDING 11 423 N MAIN ST MIDDLEBURY, INDIANA 46540-9218

o Integrity

o Safety

o Quality

Customer Service

1/11/2021

Pursuant to USC49CFR §577.13 – Notification to Dealerships and Distributors – Paragraph B

"It is a violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied. Substantial civil penalties apply to violations of this law." —Forest River motorized and towable products are contained in this section-

CANADA: Pursuant to the Canadian Motor Vehicle Safety Act, section 5

<u>Companies who sell new non-complying vehicles may be in violation of the Motor Vehicle Safety Act. Substantial</u> penalties apply to violations of this law. This notice is being sent to you in accordance with the requirements of the Motor Vehicle Safety Act. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

Forest River – Office of Corporate Compliance ("OCC") has decided that a safety defect exists in certain 2020-2021 Berkshire, 2020 Sportscoach, Pursuit, and Mirada Class A Motorhomes, 2019-2020 Concorde and Orion, 2020-2021 Cross Trek, 2019-2021 Freelander, Leprechaun and Prism, 2020 Dynamax Class C Motorhomes, 2019 Chaparral and Shasta Fifth Wheel, 2008 Salem, 2020 Salem and Wildwood Travel Trailer recreational vehicles. Forest River is recalling the defect model(s) to ensure the safety of our future retail consumers and your dealership. Forest River apologizes for any inconvenience this action may cause your dealership; however, safety continued satisfaction and our commitment to building great products are of the utmost importance to Forest River.

The identified VIN referenced in the attached document(s).

DEFECT/NONCOMPLIANCE:

As Per Dometic Corporation Recall 20E071 - The saddle valve securement bolts may be overtightened, which may cause damage to the O-ring seal between the saddle valve and the manifold, which can cause a continuous gas leak.

EVALUATION OF RISK:

The overtightening of the saddle valve securement bolt onto the manifold of the stove may cause a gas leak which may ignite and cause a fire, property damage, death or injury.

SERVICE PROCEDURE:

Dealership Service Department Service procedures for addressing the Dometic stove saddle valve is on Dealer Connect.

WHAT IS THE PART NUMBER OF THE REMEDY KIT?

See Remedy Instructions on Dealer Connect

PARTS AND RETURN:

Pictures are required for the remedy and/or inspection after installation. Pictures of the remedy are a condition of payment in which must be provided with a claim against the repair code(s).

DEALER REPAIR CODES: Dealer Connect

UNITED STATES	CANADA	REPAIR CODE	DESCRIPTION	ALLOWABLE HOUR(S)
20V727	2020-563	RC-029-05-00-003855	INSPECT FOR DOMETIC STOVE	.2
20V727	2020-563	RC-029-01-00-003856	REPAIR DOMETIC STOVE	.75

IMPORTANT SAFETY RECALL

HELPFUL CONTACT INFORMATION:				
CONTACT	PHONE			
COACHMEN CLASS C	(574) 825-8602			
COACHMEN CLASS A	(574) 825-8212			
DYNAMAX	(574) 262-3474			
SALEM AND WILDWOOD	(574) 534-3167			
BERKSHIRE	(574) 522-1368			
SHASTA	(574) 821-1311			
CHAPARRAL	(574) 825-8360			
DOMETIC CUSTOMER SERVICE	(888) 943-4905			

HELPFUL CONTACT INFORMATION

The Recall shall be considered the utmost priority to remedy the 2020-2021 Berkshire, 2020 Sportscoach, Pursuit, and Mirada Class A Motorhomes, 2019-2020 Concorde and Orion, 2020-2021 Cross Trek, 2019-2021 Freelander, Leprechaun and Prism, 2020 Dynamax Class C Motorhomes, 2019 Chaparral and Shasta Fifth Wheel, 2008 Salem, 2020 Salem and Wildwood Travel Trailer recreational vehicles in question. **The retail consumer shall not be charged** any amount of monies for remedy to their 2020-2021 Berkshire, 2020 Sportscoach, Pursuit, and Mirada Class A Motorhomes, 2019-2020 Concorde and Orion, 2020-2021 Berkshire, 2020 Sportscoach, Pursuit, and Mirada Class A Motorhomes, 2019-2020 Concorde and Orion, 2020-2021 Cross Trek, 2019-2021 Freelander, Leprechaun and Prism, 2020 Dynamax Class C Motorhomes, 2019 Chaparral and Shasta Fifth Wheel, 2008 Salem, 2020 Salem and Wildwood Travel Trailer recreational vehicles listed under this Recall.

If your dealership has already performed the remedy to 2020-2021 Berkshire, 2020 Sportscoach, Pursuit, and Mirada Class A Motorhomes, 2019-2020 Concorde and Orion, 2020-2021 Cross Trek, 2019-2021 Freelander, Leprechaun and Prism, 2020 Dynamax Class C Motorhomes, 2019 Chaparral and Shasta Fifth Wheel, 2008 Salem, 2020 Salem and Wildwood Travel Trailer recreational vehicles, your dealership is entitled to the reimbursement as stated above by filing a claim using the indicated repair code(s). If the remedy needs to be performed on an out of warranty 2020-2021 Berkshire, 2020 Sportscoach, Pursuit, and Mirada Class A Motorhomes, 2019-2020 Concorde and Orion, 2020-2021 Berkshire, 2019-2021 Freelander, Leprechaun and Prism, 2020 Dynamax Class C Motorhomes, 2019 Chaparral and Shasta Fifth Wheel, 2008 Salem, 2020 Salem and Wildwood Travel Trailer recreational vehicles in which the VIN falls under as stated in the identified VIN listing, your dealership is entitled to the reimbursement as stated above by filing a claim using the indicated repair code(s).

Notice:

In no manner shall a Forest River Product Owner or Coachmen Product Owner be charged any fee(s) for scheduling, conduction or completion of the recall. Additionally, all dealership(s) that are Forest River and/or Coachmen dealership(s) are Federally Mandated to perform the recall once presented with this recall whether by the Owner or Dealership receipt of this letter, without denial of service to the Owner. Lastly, denial of a remedy for this recall is a Federal Violation punishable by law resulting substantial fines and/or civil penalties.

Federal Regulation requires that any lessor receiving this Recall must forward a copy of this notice to the lessee within ten days. If your dealership no longer owns this vehicle, please inform the Warranty Manager of the product listed above of the change of ownership.

Sincerely,

Cherie Schmucker

Forest River, Inc. Office Manager Office of Corporate Compliance