

December 7, 2020

Mr. Cory Hoffman General Manager Toyota Motor Engineering & Manufacturing 19001 South Western Ave Torrance, CA 90501

Subject: Damaged Steering Column Can Interfere With Air Bag

Dear Mr. Hoffman:

This letter serves to acknowledge Toyota Motor Engineering & Manufacturing's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TOYOTA/AVALON/2020-2021 TOYOTA/AVALON HYBRID/2020 TOYOTA/RAV4/2020 TOYOTA/RAV4 HYBRID/2020

Mfr's Report Date: November 25, 2020

NHTSA Campaign Number: 20V-734

Components: AIR BAGS:FRONTAL STEERING:COLUMN

Potential Number of Units Affected: 161

Problem Description:

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2020-2021 Toyota Avalon and 2020 Avalon Hybrid, RAV4, and RAV4 Hybrid vehicles. Breakaway pins within the steering column, designed to absorb energy and reduce injury during a crash, could have been damaged during production, possibly affecting the performance of the driver's air bag in the event of a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Consequence:

In the event of a crash, an air bag that does not deploy as designed can increase the risk of injury.

Remedy:

Toyota will notify owners, and dealers will replace the steering column, free of charge. The recall is expected to begin January 18, 2021. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's number for this recall is 20TB17/20TA17.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150SS 20V-734



Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Toyota's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please ensure the following requirements are met:

The percentage of products estimated to contain the defect or noncompliance (49 CFR 573.6 (c)(4)). If less than 1%, amend your filing to state 1% and provide the actual calculated amount in the first product text box.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Shiver who may be reached by phone at (202) 366-7401, or by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff Chief, Recall Management Division Office of Defects Investigations Enforcement

