

# Recall Quarterly Report

## 20V-759

**Manufacturer Name :** Nissan North America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 20V-759 /  
**Recall Subject :** Exposed Wire in Engine Harness Can Cause Stall  
**Owner Notification Beginning Date :** JAN 27, 2021  
**Owner Notification End Date:** JAN 27, 2021



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 3        | OCT 27, 2021    | 2021-3         | 7,583             | 5,475          | 0                 | 0             |
| 2        | JUL 30, 2021    | 2021-2         | 7,583             | 4,858          | 0                 | 0             |
| 1        | APR 29, 2021    | 2021-1         | 7,583             | 3,352          | 0                 | 0             |

This Document Last Updated : OCT 29, 2021

### Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.