

HONDA

American Honda Motor Co., Inc.
1919 Torrance Boulevard
Torrance, CA 90501-2746
Phone (310) 783-2000

December 15, 2020

Mr. Jeffrey Giuseppe
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attn: Recall Management Division (NVS-215)
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Re: NHTSA Recall No. 20V-769
Part 573, Amended Defect Information Report
2013-2015 Model Year Honda Accord
Drive Shaft

Dear Mr. Giuseppe:

In accordance with the National Traffic and Motor Vehicle Safety Act and 49 CFR Part 573 Defect and Noncompliance and Responsibility Reports, Honda is submitting the enclosed amended Defect Information Report regarding NHTSA recall number 20V-769 originally submitted on December 10, 2020. Washington, D.C. is being included to the list of states affected by this regional recall.

If you have any questions about this report, please feel free to contact me.

Sincerely,

AMERICAN HONDA MOTOR CO., INC.



Jeff Chang
Senior Manager
Product Regulatory Office

JC:wvt

Amended Defect Information Report

573.6(c)(2)

Description of how the vehicles being recalled differ from similar vehicles not included in the recall:

The recall is specific to vehicles sold or ever registered in the salt-belt region (Connecticut, Delaware, Illinois, Indiana, Iowa, Kentucky, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, Virginia, Washington, D.C., West Virginia, and Wisconsin). There have been no reports of occurrences outside the salt-belt region.