## **Recall Quarterly Report**

20V-774

Manufacturer Name : Kawasaki Motors Corp., U.S.A. NHTSA Recall No. / MFR Recall No. : 20V-774 /MC20-13 Recall Subject : Camshaft Chain Tensioner Improperly Heat-Treated Owner Notification Beginning Date : DEC 21, 2020 Owner Notification End Date: DEC 21, 2020



| Report # | Submission Date | Report<br>Quarter | Recall<br>Population | Total<br>Remedied | Total<br>Unreachable | Total<br>Removed |
|----------|-----------------|-------------------|----------------------|-------------------|----------------------|------------------|
| 2        | APR 05, 2021    | 2021-1            | 1,770                | 1,335             | 0                    | 33               |
| 1        | JAN 08, 2021    | 2020-4            | 1,770                | 345               | 0                    | 0                |

This Document Last Updated : APR 14, 2021

## **Definitions** :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.

The information contained in this report was submitted pursuant to 49 CFR §573.7