

# Part 573 Safety Recall Report

## 20V-796

**Manufacturer Name :** Jayco, Inc.**Submission Date :** JAN 05, 2021**NHTSA Recall No. :** 20V-796**Manufacturer Recall No. :** 9903529**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

**Population :**

Number of potentially involved : 1,656

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2016-2020 Jayco Class C Motorhome Seneca

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Production records from MY 2016-2020 - Affected serial number list uploaded to portal

Production Dates : APR 01, 2015 - JUL 17, 2019

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : : The mounting brackets for the leveling system hydraulic pump and reservoir require reinforcement.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Bracket failure may allow the pump and reservoir to come in contact with the ground, creating potential of either complete separation and/or the possibility of hydraulic fluid loss.

Description of the Cause : NR

Identification of Any Warning NR  
that can Occur :**Involved Components :**

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

### Supplier Identification :

#### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

### Chronology :

10/22/20 Monthly Safety Steering Committee Meeting

- Review of details associated with the Greyhawk/Redhawk Support Bracket
- Vote for additional recall on Greyhawk and Redhawk
- Review of data on all units/claims that having leveling systems
- Authorization to conduct formal investigation and analysis on the Seneca Bracket

12/10/20 Monthly Safety Steering Committee Meeting (Combined November/December)

- Review of formal investigation and analysis on Seneca Brackets
- Found 12 units with failures
- Failure mode is very similar to Greyhawk/Redhawk
- Same concern level for consumer safety
- Design FEA review was preliminary and was not 100% complete
- Request additional discussion after Design FEA is complete on current design and the design that was on earlier units (prior to 7/17/19).

12/14/20 Design FEA Complete

- Stresses and loads seen in the Design FEA are consistent with failures observed on at least three units where pictures were available.
- Additional welds added on 7/17/19 between the Leveling Support Channel and the bottom flange of the chassis main rail show significant improvement in stresses and load observed in design FEA.
- Design FEA correlation to failure photographs. Recommend recalling all Seneca brands produced prior to the 7/17/19 design change date.

12/15/20 Safety Committee reviewed all details and agreed that safety recall is required.

### Description of Remedy :

Description of Remedy Program : Not know at this time

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : 7-17-2019 - new specifications placed in action to place extra weld where the hydraulic system channel rests on the bottom flange of the chassis rail.

### Recall Schedule :

Description of Recall Schedule : Jayco will release once remedy is know and parts allocated

Planned Dealer Notification Date : FEB 15, 2021 - FEB 15, 2021

Planned Owner Notification Date : FEB 15, 2021 - FEB 15, 2021

\* NR - Not Reported