OMB Control No.: 2127-0004

Recall Quarterly Report

20V-806

Manufacturer Name: Daimler Trucks North America, LLC NHTSA Recall No. / MFR Recall No.: 20V-806 /FL-871 Recall Subject: Hydraulic Caliper Tie Bar May Be Loose Owner Notification Beginning Date: FEB 18, 2021 Owner Notification End Date: MAR 17, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	OCT 21, 2021	2021-3	278	230	0	0
2	JUL 28, 2021	2021-2	278	196	0	0
1	APR 14, 2021	2021-1	278	164	0	0

This Document Last Updated: OCT 28, 2021

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3^{rd} quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.