

Recall Quarterly Report

20V-807

Manufacturer Name : Daimler Trucks North America, LLC

NHTSA Recall No. / MFR Recall No. : 20V-807 / FL-871

Recall Subject : Hydraulic Caliper Tie Bar May Be Loose

Owner Notification Beginning Date : FEB 18, 2021

Owner Notification End Date: MAR 17, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JUL 28, 2021	2021-2	80	31	0	0
1	APR 14, 2021	2021-1	80	26	0	0

This Document Last Updated : AUG 11, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.