



November 2021

Dealer Information for:

Equipment Safety Recall Y82 NHTSA 21E-093 Occupant Restraint Controller

Subject

FCA US LLC (FCA US) has announced an equipment safety recall on certain Mopar Occupant Restraint Controller (ORC) Module part numbers:

68518544AE

68518543AE

68518542AF

68476781AB

68425814AE

68425813AB

Dealers may have purchased an ORC Module intended for the **2021 (WL) Jeep® Grand Cherokee and 2022 (WS) Wagoneer/Grand Wagoneer.**

The Occupant Restraint Controller (ORC) module may have incorrect software. The airbag warning indicator may not illuminate to notify the operator of possible compromised airbag system functionality. If specific ORC internal faults are active, then a diagnostic trouble code (DTC) will not be set and the airbag warning indicator may not illuminate. The internal faults will disable deployment of both the driver and passenger airbag squib (related to airbag venting post deployment) and knee airbags. **Reduced occupant protection in the event of a crash may result in an increased risk of injury to motor vehicle occupants.**

Parts Information

FCA US is conducting a voluntary equipment safety recall on all affected parts to repurchase suspect ORCs.

All dealers are required to return all affected purchased ORC modules in order be repurchased.

Additional Information

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

Customer Services / Field Operations
FCA US LLC