## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

21V-002

**Manufacturer Name:** Marion Body Works Inc.

NHTSA Recall No. / MFR Recall No.: 21V-002 /20E-034 Recall Subject: Lift Gate License Plate Light Alignment Owner Notification Beginning Date: JAN 11, 2021

**Owner Notification End Date: JAN 11, 2021** 



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 05, 2021	2021-1	1	0	0	0

This Document Last Updated: APR 05, 2021

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.