

Recall Quarterly Report

21V-018

Manufacturer Name : Daimler Trucks North America, LLC
NHTSA Recall No. / MFR Recall No. : 21V-018 / FL-873
Recall Subject : Caliper Mounting Bolt Not Tightened Properly
Owner Notification Beginning Date : MAR 17, 2021
Owner Notification End Date: MAR 17, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 14, 2021	2021-1	133	8	0	0

This Document Last Updated : APR 28, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
Recall Population : The total number of products recalled by the manufacturer.
Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.
Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.
Total Removed : Products that have been scrapped, stolen, or exported.