

Recall Quarterly Report

21V-027

Manufacturer Name : Volkswagen Group of America, Inc.
NHTSA Recall No. / MFR Recall No. : 21V-027 / 48P7
Recall Subject : Detached Circlip Can Cause Steering To Lockup
Owner Notification Beginning Date : FEB 28, 2021
Owner Notification End Date:



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	APR 29, 2021	2021-1	1	1	0	0

This Document Last Updated : MAY 05, 2021

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
Recall Population : The total number of products recalled by the manufacturer.
Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.
Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.
Total Removed : Products that have been scrapped, stolen, or exported.