

U.S. Department of Transportation

National Highway Traffic Safety Administration

February 12, 2021

Mr. Greg Gunther Department Manager VCA Mercedes-Benz USA, LLC 13470 International Parkway Jacksonville, FL 32218 NEF-150JK 21V-056

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Reverse Light Remains Illuminated/FMVSS 108

Dear Mr. Gunther:

This letter serves to acknowledge Mercedes-Benz USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES-BENZ/GLE350/2020 MERCEDES-BENZ/GLE450/2020

Mfr's Report Date: February 5, 2021

NHTSA Campaign Number: 21V-056

Components:

EXTERIOR LIGHTING:BACK UP LIGHTS

Potential Number of Units Affected: 8,186

Problem Description:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2020 GLE350 and GLE450 vehicles. The lighting control unit may malfunction and cause the left exterior reverse light to remain illuminated after the transmission is shifted into a different gear. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

Consequence:

If the reverse light remains illuminated in a gear other than reverse, it may cause confusion about the driver's intention to other motorists, and increase the risk of a crash.

Remedy:

MBUSA will notify owners, and dealers will replace the lighting control unit, free of charge. The recall is expected to begin April 6, 2021. Owners may contact MBUSA customer service at 1-800-367-6372.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigations

Slace Andy

Enforcement

