## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

21V-172

**Manufacturer Name:** Forest River, Inc.

NHTSA Recall No. / MFR Recall No.: 21V-172 /121-1305 Recall Subject: Cooktop Flame May Become Inverted Owner Notification Beginning Date: MAR 31, 2021

**Owner Notification End Date:** APR 05, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JUL 12, 2021	2021-2	86	28	0	0
1	APR 21, 2021	2021-1	86	0	0	0

This Document Last Updated: JUL 13, 2021

## **Definitions:**

 $Report\ Quarter:\ The\ quarter\ the\ manufacturer\ is\ reporting\ recall\ completion\ figures\ (e.g.\ 2012-3\ means\ the\ 3^{\bf rd}\ quarter\ of\ 2012).$ 

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.