OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-184

Manufacturer Name: Jayco, Inc. **Submission Date:** MAR 17, 2021 NHTSA Recall No.: 21V-184 Manufacturer Recall No.: 9901566



Manufacturer Information:

Manufacturer Name: Jayco, Inc.

Address: 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone: 800-283-8267

Population:

Number of potentially involved: NR Estimated percentage with defect: NR

Vehicle Information:

Vehicle 1: 2019-2020 TT FW ytbd

Vehicle Type: TRAILERS

Body Style: Power Train: NR

Descriptive Information: We are working to match Jayco products to Dometic PO report for 20,000+ recalled

cooking stoves - will edit 573 upon completion

Production Dates: JUN 01, 2018 - SEP 01, 2020

VIN Range 1 : Begin : NR End: NR

Not sequential

Description of Defect:

Description of the Defect: Dometic cooking stoves Series S31,R1731 and R2131 manufactured May 2018

- July 9, 2020 - after some period of usage, occupant may smell gas near the stove when it is not in operation. If the user or other servicer that attempts to tighten the bolts that hold the valves under the stove burners, the tightening action can cause irreversible damage to the O-ring seal at the valve(s), resulting

in a continuous gas leak.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Continuous gas lead could result in explosion / fire.

Description of the Cause: NR Identification of Any Warning NR that can Occur:

Involved Components:

Component Name 1: cooking stovbe

Component Description: R1731 R2131

Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: Dometic Corp.

Address: 5155 Verdant Drive

Elkhart Indiana 46516

Country: United States

Chronology:

10-1-2020 Thor released information to Jayco that Dometic was filing a safety recall on model S31 R1731 and R2131 cooking stoves. Jayco waited for official notice with listing of stove sold to any of Jayco divisions - While we could see information filed on NHTSA portal. JAYCO COMPLIANCE DID NOT RECEIVE OFFICIAL RECALL NOTICE from Dometic. Jayco Compliance reached out to Dometic for list of the recall stoves (if any) sold to any Jayco Division - multiple times from Nov 2020 through March 5, 2021 when Jayco requested a formal letter stating none of the recalled stoves were sold to any Jayco division so we could close the incident.. March 17.2021 Jayco Compliance receive an email from Dometic noting 20,000+ recalled stove serial numbers sold to numerous Jayco Plants. Jayco is currently matching the stove serial numbers to Jayco Towable Products. .

Description of Remedy:

Description of Remedy Program: A Dometic authorized service center will perform the recall remedy at no

charge to current owner.

Manifold Bolt and Valve Seal replacement.

How Remedy Component Differs Orange sticker - notes recall remedy was already performed.

from Recalled Component :

Identify How/When Recall Condition None of Jayco production lines currently use any of the recalled cooking

was Corrected in Production: stoves.

Recall Schedule:

Description of Recall Schedule: Jayco will work with Dometic how to administer recall

Planned Dealer Notification Date: APR 30, 2021 - APR 30, 2021

Part 573 Safety Recall Report

21V-184

Page 3

Planned Owner Notification Date: APR 30, 2021 - APR 30, 2021

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573