## **Recall Quarterly Report**

21V-214

Manufacturer Name : Shyft Group NHTSA Recall No. / MFR Recall No. : 21V-214 /21-07 Recall Subject : Steering Output Shaft May Disconnect Owner Notification Beginning Date : MAR 31, 2021 Owner Notification End Date: MAR 31, 2021



| Report # | Submission Date | Report<br>Quarter | Recall<br>Population | Total<br>Remedied | Total<br>Unreachable | Total<br>Removed |
|----------|-----------------|-------------------|----------------------|-------------------|----------------------|------------------|
| 1        | APR 26, 2021    | 2021-1            | 37                   | 6                 | 0                    | 0                |

This Document Last Updated : APR 27, 2021

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.