## OMB Control No.: 2127-0004

## **Recall Quarterly Report**

21V-307

**Manufacturer Name:** Arcimoto Inc

NHTSA Recall No. / MFR Recall No.: 21V-307 / Recall Subject: Failure Mode May Cause Over Steer Owner Notification Beginning Date: MAY 27, 2021

**Owner Notification End Date:** JUN 04, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JAN 28, 2022	2021-4	261	207	0	4
2	OCT 25, 2021	2021-3	261	115	0	4
1	JUL 22, 2021	2021-2	261	53	0	4

This Document Last Updated: JAN 28, 2022

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.