

Recall Quarterly Report**21V-309**

Manufacturer Name : Chrysler (FCA US, LLC)
NHTSA Recall No. / MFR Recall No. : 21V-309 /Y24
Recall Subject : Rotor and Shaft May Separate Causing a Loss of ABS
Owner Notification Beginning Date : JUN 29, 2021
Owner Notification End Date: JUN 29, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 20, 2021	2021-2	9	0	0	0

This Document Last Updated : JUL 21, 2021

Definitions :

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.