

U.S. Department of Transportation

National Highway Traffic Safety Administration

May 18, 2021

Ms. Allison Freeman Spartan Fire, LLC 1541 Reynolds Road Charlotte, MI 48813 1200 New Jersey Avenue SE Washington, DC 20590

NEF-107MR 21V-329

Subject: Solenoid Corrosion may Hinder Fire Fighting

Dear Ms. Freeman:

This letter serves to acknowledge Spartan Fire, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

SPARTAN FIRE/GLADIATOR/2009-2021 SPARTAN FIRE/METROSTAR/2009-2021

Mfr's Report Date: May 10, 2021

NHTSA Campaign Number: 21V-329

Components:

ELECTRICAL SYSTEM

Potential Number of Units Affected: 2.130

Problem Description:

Spartan Fire, LLC is recalling certain 2009-2021 Gladiator and MetroStar emergency vehicles. The fire water pump solenoid may corrode internally, causing a loss of power to the pump control module.

Consequence:

A loss of power to the pump control module can cause a loss of water pressure for fighting fires, increasing the risk of injury.

Remedy:

Dealers will replace suspect solenoids, free of charge. Owner notification letters are expected to be mailed on June 21, 2021. Owners may contact Spartan Fire customer service at 1-517-543-6400.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Spartan Fire, LLC's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

