## **Recall Quarterly Report**

21V-357

Manufacturer Name : Daimler Trucks North America, LLC NHTSA Recall No. / MFR Recall No. : 21V-357 /FL-887 Recall Subject : Dislodged Headlight May Cause Fire Owner Notification Beginning Date : JUL 09, 2021 Owner Notification End Date: JUL 09, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	OCT 29, 2021	2021-3	72,510	25,391	0	22

This Document Last Updated : NOV 01, 2021

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.