

**Recall Quarterly Report****21V-364**

**Manufacturer Name :** Motor Coach Industries  
**NHTSA Recall No. / MFR Recall No. :** 21V-364 /R21-009  
**Recall Subject :** High Pressure Fuel Rail Assembly May Leak Fuel  
**Owner Notification Beginning Date :** JUN 28, 2021  
**Owner Notification End Date:** JUL 02, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JAN 28, 2022	2021-4	1,845	397	0	1
2	OCT 28, 2021	2021-3	1,845	162	0	1
1	JUL 29, 2021	2021-2	1,845	0	0	1

This Document Last Updated : FEB 02, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.