IMPORTANT SAFETY RECALL



NHTSA RECALL: 21V374 CANADA RECALL: 2021-306 FR ID: 410-1350

<<CITY>>, <<ST>> <<ZIP-XXX>>

<<DEALERNAME>>

<<ADDRESS>>

DEPARTMENT OF COMPLIANCE VEHICLE SAFETY AND RECALL MANAGEMENT BUILDING 11 423 N MAIN ST MIDDLEBURY, INDIANA 46540-9218

Integrity

Safety

o Quality

Customer Service

06/09/2021

Pursuant to USC49CFR §577.13 – Notification to Dealerships and Distributors – Paragraph B

"It is a violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied. Substantial civil penalties apply to violations of this law." —Forest River motorized and towable products are contained in this section-

CANADA: Pursuant to the Canadian Motor Vehicle Safety Act, section 5

<u>Companies who sell new non-complying vehicles may be in violation of the Motor Vehicle Safety Act. Substantial</u> penalties apply to violations of this law. This notice is being sent to you in accordance with the requirements of the Motor Vehicle Safety Act. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

Forest River – Office of Corporate Compliance ("OCC") has decided that a safety defect exists in certain 2021 Columbus Fifth Wheel recreational vehicles. Forest River is recalling the defect model(s) to ensure the safety of our future retail consumers and your dealership. Forest River apologizes for any inconvenience this action may cause your dealership; however, safety continued satisfaction and our commitment to building great products are of the utmost importance to Forest River.

The identified VIN referenced in the attached document(s). The designated Date range of production is 4/14/2021 through 5/20/2021.

DEFECT/NONCOMPLIANCE:

The breakaway switch power lead is wired to the auxiliary side of the 30-amp breaker. Without constant power to the switch, it may not engage when needed and consequently not allow the trailer brakes to activate.

EVALUATION OF RISK:

This condition may lead to the failure of the brake-away switch to activate in an emergency. Which may lead to a crash resulting in property damage, injury and/or death.

SERVICE PROCEDURE:

Dealership Service Department Service procedures for addressing the incorrectly wired breakaway switch can be found on Dealer Connect. The remedy will include wiring the breakaway switch to constant power.

DEALER REPAIR CODES: Dealer Connect

UNITED STATES	CANADA	REPAIR CODE	DESCRIPTION	ALLOWA BLE HOUR(S)
21V374	2021-306	RC-036-05-00-004062	INSPECT BREAKAWAY SWITCH	.10
21V374	2021-306	RC-036-22-00-004063	INSPECT AND REWIRE BREAKAWAY SWITCH	.50

HELPFUL CONTACT INFORMATION:						
CONTACT	PHONE	EMAIL				
Columbus Customer Service	(574) 821-1487	columbuscustomerservice@forestriverinc.com				

IMPORTANT SAFETY RECALL

The Recall shall be considered the utmost priority to remedy the 2021 Columbus Fifth Wheel in question. **The retail consumer shall not be charged** any amount of monies for remedy to their 2021 Columbus Fifth Wheel listed under this Recall.

If your dealership has already performed the remedy to 2021 Columbus Fifth Wheel, your dealership is entitled to the reimbursement as stated above by filing a claim using the indicated repair code(s). If the remedy needs to be performed on an out of warranty 2021 Columbus Fifth Wheel in which the VIN falls under as stated in the identified VIN listing, your dealership is entitled to the reimbursement as stated above by filing a claim using the indicated repair code(s).

Notice:

In no manner shall a Forest River Product Owner or Coachmen Product Owner be charged any fee(s) for scheduling, conduction or completion of the recall. Additionally, all dealership(s) that are Forest River and/or Coachmen dealership(s) are Federally Mandated to perform the recall once presented with this recall whether by the Owner or Dealership receipt of this letter, without denial of service to the Owner. Lastly, denial of a remedy for this recall is a Federal Violation punishable by law resulting substantial fines and/or civil penalties.

Federal Regulation requires that any lessor receiving this Recall must forward a copy of this notice to the lessee within ten days. If your dealership no longer owns this vehicle, please inform the Warranty Manager of the product listed above of the change of ownership.

Sincerely,

Cherie Schmucker

Forest River, Inc. Office Manager Office of Corporate Compliance