

# Recall Quarterly Report

## 21V-444

**Manufacturer Name :** Forest River, Inc.

**NHTSA Recall No. / MFR Recall No. :** 21V-444 /501-1366

**Recall Subject :** LP/CO Detector Installed Incorrectly

**Owner Notification Beginning Date :** JUN 24, 2021

**Owner Notification End Date:** JUN 24, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JAN 30, 2022	2021-4	10	7	0	0
2	OCT 25, 2021	2021-3	10	6	0	0
1	JUL 12, 2021	2021-2	10	0	0	0

This Document Last Updated : JAN 31, 2022

### Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.