

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS5876  
URGENT - DISTRIBUTE IMMEDIATELY

Date: July 22, 2021

Subject: REVISION: N212340860-01 - Safety Recall  
Driver Airbag Fastener Missing  
Revised Service Procedure, Parts, Warranty, Add of Customer Letter

Models: 2022 Chevrolet Bolt EV  
2022 Chevrolet Bolt EUV

To: All General Motors Dealers

This bulletin has been revised to update the service procedure, add part numbers, update the warranty information section, and add the customer letter. Please discard all copies of bulletin N212340860.

**Question and Answer Document (Q&A)**

Attached to this message you will find a document that addresses the ten most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

**Customer Letter Mailing**

The customer letter mailing will begin August 4, 2021.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS